

ANNUAL REPORT OF OPERATIONS FOR YEAR 2018**Idaho Fish Processors Permit**

I. Facility Name: Evaqua Farms LLC	NPDES # IDG132004
Operator Name (Permittee): Evaqua Farms LLC	Phone: 208-326-3100
Address: PO Box AG Filer, ID 83328	Fax: 208-326-5935
	E-Mail: info@evaquafarms.com
Owner Name (if different from operator):	Phone:

II. Annual Production: Number of pounds of fish processed in the year 7,159,777 pounds

III. Noncompliance Summary.

Include description & dates of noncompliance, the reasons for such incident, and the steps taken to correct the problem. Attach additional pages, if necessary.

None

IV. Best Management Practices (BMP) Plan

BMP Plan has been reviewed this year.

BMP plan fulfills the requirements set forth in the permit:

Summarize changes in the BMP Plan since last annual report:

☒ Yes ☐ No
☒ Yes ☐ No

V. Land application of solids and irrigation with wastewater

Attach Maps of Application Sites (Note: IDAPA 58.01.02.650 requires IDEQ approval for solids disposal on land.)

Date	Location and Acreage of Application	Solids Applied in Cubic Yards or Pounds		Wastewater Applied in Gallons	
2/11/18 10/10/18	All on farm grounds, 7 Acre +/-	450	338	18,000	13,500
3/21/18 10/16/18		338	422	13,500	16,875
4/21/18 10/20/18		507	225	20,250	9,000
5/19/18		248	All in pounds	9,900	
5/24/18		281		11,250	
5/30/18		225		9,000	
6/10/18		450		18,000	
6/30/18		225		9,000	
7/13/18		432		17,250	
7/20/18		338		13,500	
7/27/18		338		13,500	
8/9/18		225		9,000	
8/13/18		225		9,000	
8/22/18		469	18,750		
8/25/18		338	13,500		
9/1/18		244	9,750		
9/21/18	563	22,500			
Yearly Total		6,881 LBS		275,025 Gallons	

ICFS
2/25/19
JM

VI. Chemical Usage (Including pesticides and drugs)

Chemical	Date or # days used	Maximum concentration in effluent (actual or estimated)
T-Chlor 12.5	260	Less than 0.01 mg/L (actual)
Alka Foam	260	64 mg/L (estimated)
Sani-T	260	5.1 mg/L (estimated)
Carbo-Chlor	260	12.2 mg/L (estimated)
Pro-Quat	260	14.7 mg/L (estimated)
FS-100	260	4.6 mg/L (estimated)
Estimates reflect maximum in effluent prior to the treatment lagoon. Actuals represent measurements taken at lagoon discharge.		

VII. Inspections and Repairs for Wastewater Treatment Systems

Date Inspected	Date Repaired	Description of system inspected and/or repaired
9/10/20108 Daily	9/10/2018	Drive belt for blower pump replaced. All pumps required for the system to operate are checked daily during operation.

VIII. Signature & Certification

"I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure the qualified personnel properly gather and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations."

Signature:



Title/Company:



Print Name:



Date:



EVAQUA FARMS, LLC

SITE MAP AND LAND APPLICATION AREAS

